



LEFT SIDE ELEVATION



REAR ELEVATION



RIGHT SIDE ELEVATION



FRONT ELEVATION

TOWNSHIP PUD
COF #5841
ARCHITECTURAL ELEVATIONS

HARMONY SOUTHERN CARE
SOUTHERN CARE, INC.
1020 HARMONY HILLS DRIVE - FRANKLIN, TN

LON F. RABY
ARCHITECT
201A Woodmont Circle - Nashville, TN 37205
615-479-7040 - fax 615-457-3310



DATE
May 7, 2015
September 4, 2015
SHEET NO.
A1.0
19 of 20 Sheets



HARDI-PLANK SIDING = BEHR
"CANYON VIEW ECC-20-1"

GUTTERS/DOWNSPOUTS
AND EXTERIOR TRIM = BEHR
"ULTRA PURE WHITE"

HVAC UNIT
TYPICAL

ROOFING = TAMKO HERITAGE
PREMIUM "RUSTIC SLATE"

BRICK = HENRY BRICK CO
"CYPRESS POINT"


TOWNSHIP PUD
COF #5841
BUILDING MATERIALS

HARMONY SOUTHERN CARE
SOUTHERN CARE, INC.
1020 HARMONY HILLS DRIVE - FRANKLIN, TN

LON F. RABY
ARCHITECT
201A Woodmont Circle - Nashville, TN 37205
615-479-7040 - fax 615-457-3310



DATE
May 7, 2015
September 4, 2015
SHEET NO.
A1.1
20 of 20 Sheets




Front Elevation	Surface Area	Percent of Net
Gross of Wall	4139	
Net of Wall	3273	
Net Brick	1634	49.9%
Net Siding	1639	50.1%

Front Elevation
3/32" = 1'-0"

Finish Legend

Mark	Manufacture	Color
1	Field Brick	Henry Brick Cypress Point
2	Siding	James Hardie Behr - Canyon View
3	Trim	To Be Determined Behr - Ultra Pure White
4	Exterior Metal Door	To Be Determined Behr - Ultra Pure White
5	Aluminum Entry System	Stanley White
6	Asphalt Shingles	Tamco Rustic Slate
7	Columns	Permacast Behr - Ultra Pure White
8	Concrete Caps	To Be Determined Natural
9	Louver	To Be Determined Behr - Ultra Pure White




Left Elevation	Surface Area	Percent of Net
Gross of Wall	2021	
Net of Wall	1713	
Net Brick	1015	59.3%
Net Siding	698	40.7%

Left Elevation
3/32" = 1'-0"


These elevations have been designed to meet the requirements of the City of Franklin's architectural design standards and the approval of the planning commission. Changes shall not be made to the approved elevations unless approved by either the codes department or the planning commission.
Franklin Codes Department (615)794-7012
Franklin Planning Department (615)791-3212

HVAC Units, cooling and or mechanical units are located on the:	
<input checked="" type="checkbox"/>	Rooftop
<input checked="" type="checkbox"/>	Ground
<input type="checkbox"/>	None Provided



Right Elevation	Surface Area	Percent of Net
Gross of Wall	41	
Net of Wall	1713	
Net Brick	1015	59.3%
Net Siding	698	40.7%

Right Elevation
3/32" = 1'-0"



Rear Elevation	Surface Area	Percent of Net
Gross of Wall	4188	
Net of Wall	3498	
Net Brick	1672	47.8%
Net Siding	1826	52.2%

Rear Elevation
3/32" = 1'-0"

HARMONY SOUTHERN CARE
SOUTHERN CARE, INC.
1020 HARMONY HILLS DRIVE - FRANKLIN, TN

LON F. RABY
ARCHITECT
201A Woodmont Circle - Nashville, TN 37205
615-479-7040 - fax 615-457-3310

Preliminary Pricing Set
Not to be Used for Construction

DATE
September 2, 2015

SHEET NO.

A201

