

Looking Southeast at Steep Slope between Hillsboro Road Tunnel and Pump Manhole



Looking Southeast at Recently Completed Hillsboro Road Tunnel Surround and Small Retaining/Sitting Walls



Looking Southeast at Steep Slope to North of Hillsboro Road Tunnel



Looking Southeast at Recently Completed Retaining/Sitting Walls and Hillsboro Road Tunnel Surround



Looking South at Base Stone for ADA-Compliant Ramp Connecting Tunnels and Hunters Bend Elementary School



Existing, Private Property (Daycare) Retaining Wall Directly Adjacent to West Side of Proposed ADA-Compliant Ramp



Close-Up View of Base of Existing Retaining Wall